

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 1 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 2 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 3 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 4 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 5 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : STA 1+000

LOKASI : STA 1+100


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 6 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : STA 1+200

LOKASI : STA 1+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 7 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 1+400**

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 8 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 1+600**

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 9 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 1+800**

LOKASI : **STA 1+900**


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 10 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 2+000**

LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 11 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 2+200**

LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 12 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 2+400**

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 13 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 2+600**

LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 14 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 2+800**

LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 15 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 3+000**

LOKASI : **STA 3+100**



KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 16 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 3+200**

LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 17 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 3+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 3+500**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | MELDA & DAHLAN | 18 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 3+600**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 3+700**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | MELDA & DAHLAN | 19 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 3+800**

LOKASI : **STA 3+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|
| NO. RUAS II. 8 | NAMA RUAS Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY MELDA & DAHLAN | HALAMAN 20 |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 4+000**

LOKASI : **STA 4+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|
| NO. RUAS II. 8 | NAMA RUAS Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY MELDA & DAHLAN | HALAMAN 21 |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



03/10/25 14:30:53
7°28'44"S 109°31'6"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 4+200
#Survei Jalan #DPUPR Kab Banjarnegara



03/10/25 14:32:20
7°28'43"S 109°31'9"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 4+300
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+200**

LOKASI : **STA 4+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 22 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



03/10/25 14:33:50
7°28'43"S 109°31'12"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 4+400
#Survei Jalan #DPUPR Kab Banjarnegara



03/10/25 14:35:12
7°28'41"S 109°31'13"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 4+500
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+400**

LOKASI : **STA 4+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 23 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : STA 4+600

LOKASI : STA 4+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 24 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : STA 4+800

LOKASI : STA 4+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 25 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 5+000**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+100**

KONDISI PERKERASAN : Baik


LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 26 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 5+200**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+300**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 27 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





LOKASI : **STA 5+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+500**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 28 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 5+600**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 29 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





LOKASI : **STA 5+800**

LOKASI : **STA 5+900**


KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 30 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 6+000**

LOKASI : **STA 6+100**


KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

| | | | | |
|----------|---------------------|------------------------|----------------|---------|
| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 31 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





LOKASI : **STA 6+200**

LOKASI : **STA 6+300**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUKR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | DPUKR KAB.BANJARNEGARA | MELDA & DAHLAN | 32 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 6+400**

LOKASI : **STA 6+500**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 4.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3.5 M
 TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUKR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | DPUKR KAB.BANJARNEGARA | MELDA & DAHLAN | 33 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





03/10/25 15:04:33
7°28'10"S 109°31'59"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 6+600
#Survei Jalan #DPUPR Kab Banjarnegara



03/10/25 15:06:10
7°28'9"S 109°32'1"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 6+700
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 6+600**

LOKASI : **STA 6+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 34 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



03/10/25 15:07:31
7°28'9"S 109°32'3"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 6+800
#Survei Jalan #DPUPR Kab Banjarnegara



03/10/25 15:09:01
7°28'10"S 109°32'7"E
Kabupaten Banjarnegara
#Ruas II. 8 Kedungpane - Merden
#STA 6+900
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 6+800**

LOKASI : **STA 6+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 35 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





LOKASI : **STA 7+000**

LOKASI : **STA 7+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 36 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 7+200**

LOKASI : **STA 7+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY | HALAMAN |
|----------|---------------------|------------------------|----------------|---------|
| II. 8 | Kedungpane - Merden | | MELDA & DAHLAN | 37 |

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden





LOKASI : **STA 7+400**

LOKASI : **STA 7+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

| | | | | |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|
| NO. RUAS II. 8 | NAMA RUAS Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY MELDA & DAHLAN | HALAMAN 38 |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kedungpane - Merden



LOKASI : **STA 7+520**

LOKASI : **STA**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN
LEBAR PERKERASAN
TYPE PERKERASAN

| | | | | |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|
| NO. RUAS II. 8 | NAMA RUAS Kedungpane - Merden | DPUPR KAB.BANJARNEGARA | PETUGAS SURVEY MELDA & DAHLAN | HALAMAN 39 |
|-------------------|----------------------------------|------------------------|----------------------------------|---------------|