

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           0+000**

LOKASI :           **STA           0+100**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	1

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           0+200**

LOKASI :           **STA           0+300**

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	2

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           0+400**

LOKASI :           **STA           0+500**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5                 M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5                 M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	3

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           0+600**

LOKASI :           **STA           0+700**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5                 M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5                 M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	4

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           0+800**

LOKASI :           **STA           0+900**

KONDISI PERKERASAN           :     Rusak Ringan  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Berat  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	5

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           1+000**

LOKASI :           **STA           1+100**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	6

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           1+200**

LOKASI :           **STA           1+300**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	7

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



09/10/25 11:28:40  
7°20'1" S 109°41'8" E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+400  
#Survei Jalan #DPUPR Kab Banjarnegara



09/10/25 11:30:45  
7°19'58" S 109°41'8" E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+500  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           1+400**

LOKASI :           **STA           1+500**


KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	8

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



09/10/25 11:33:08  
7°19'55" S 109°41'6" E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+600  
#Survei Jalan #DPUPR Kab Banjarnegara



09/10/25 11:35:30  
7°19'54" S 109°41'3" E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+700  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           1+600**

LOKASI :           **STA           1+700**


KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	9

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



09/10/25 11:38:04  
7°19'52"S 109°41'4"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+800  
#Survei Jalan #DPUPR Kab Banjarnegara



09/10/25 11:39:56  
7°19'50"S 109°40'58"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 1+900  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           1+800**

LOKASI :           **STA           1+900**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	10

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



09/10/25 11:42:24  
7°19'48"S 109°40'56"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 2+000  
#Survei Jalan #DPUPR Kab Banjarnegara



09/10/25 11:45:07  
7°19'46"S 109°40'53"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 2+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           2+000**

LOKASI :           **STA           2+100**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	11

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           2+200**

LOKASI :           **STA           2+300**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	12

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           2+400**

LOKASI :           **STA           2+465**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     3            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	13

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           2+500**

LOKASI :           **STA           2+525**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN       :       3                M  
TYPE PERKERASAN       :       Aspal

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN       :       5                M  
TYPE PERKERASAN       :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	14

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           2+600**

LOKASI :           **STA           2+700**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN       :       5                M  
TYPE PERKERASAN       :       Aspal

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN       :       5                M  
TYPE PERKERASAN       :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	15

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           2+800**

LOKASI :           **STA           2+900**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	16

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           3+000**

LOKASI :           **STA           3+100**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	17

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA                   3+200**

KONDISI PERKERASAN           :     Baik

LEBAR PERKERASAN            :     5                   M

TYPE PERKERASAN             :     Aspal

LOKASI :           **STA                   3+300**

KONDISI PERKERASAN           :     Baik

LEBAR PERKERASAN            :     5                   M

TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	18

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA                   3+400**

KONDISI PERKERASAN           :     Baik

LEBAR PERKERASAN            :     5                   M

TYPE PERKERASAN             :     Aspal

LOKASI :           **STA                   3+500**

KONDISI PERKERASAN           :     Rusak Ringan

LEBAR PERKERASAN            :     5                   M

TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	19

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           3+600**

KONDISI PERKERASAN           :    **Baik**

LEBAR PERKERASAN            :    **5                    M**

TYPE PERKERASAN             :    **Aspal**

LOKASI :           **STA           3+700**

KONDISI PERKERASAN           :    **Sedang**

LEBAR PERKERASAN            :    **5                    M**

TYPE PERKERASAN             :    **Aspal**

NO. RUAS <b>III. 1</b>	NAMA RUAS <b>Gripit - Kalibening</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>20</b>
---------------------------	---	-------------------------------	---	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           3+800**

KONDISI PERKERASAN           :    **Baik**

LEBAR PERKERASAN            :    **5                    M**

TYPE PERKERASAN             :    **Aspal**

LOKASI :           **STA           3+900**

KONDISI PERKERASAN           :    **Sedang**

LEBAR PERKERASAN            :    **5                    M**

TYPE PERKERASAN             :    **Aspal**

NO. RUAS <b>III. 1</b>	NAMA RUAS <b>Gripit - Kalibening</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>21</b>
---------------------------	---	-------------------------------	---	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+000**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+070**

KONDISI PERKERASAN           :       Rusak Ringan

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	22

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+100**

KONDISI PERKERASAN           :       Rusak Ringan

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+175**

KONDISI PERKERASAN           :       Rusak Berat

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	23

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+200**

LOKASI :           **STA           4+215**

KONDISI PERKERASAN           :     Rusak Berat  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Ringan  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	24

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+300**

LOKASI :           **STA           4+325**

KONDISI PERKERASAN           :     Sedang  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Berat  
 LEBAR PERKERASAN            :     5            M  
 TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	25

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+350**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+375**

KONDISI PERKERASAN           :       Rusak Berat

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	26

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           4+400**

KONDISI PERKERASAN           :       Rusak Berat

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+430**

KONDISI PERKERASAN           :       Rusak Berat

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	27

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           4+500**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+600**

KONDISI PERKERASAN           :       Baik


LEBAR PERKERASAN            :       5                M

TYPE PERKERASAN             :       Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 28
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           4+700**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5                M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           4+800**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                M

TYPE PERKERASAN             :       Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 29
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           4+900**

LOKASI :           **STA           5+000**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	30

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           5+100**

LOKASI :           **STA           5+200**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	31

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           5+300**

LOKASI :           **STA           5+400**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	32

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           5+500**

LOKASI :           **STA           5+600**

KONDISI PERKERASAN           :    Rusak Ringan  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	33

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           5+700**

LOKASI :           **STA           5+800**


KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	34

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           5+900**

LOKASI :           **STA           6+000**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	35

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           6+100**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           6+200**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	36

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           6+300**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           6+400**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	37

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           6+485**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5                   M

TYPE PERKERASAN             :       Beton

LOKASI :           **STA           6+500**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5                   M

TYPE PERKERASAN             :       Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 38
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           6+540**

KONDISI PERKERASAN           :       Rusak Ringan

LEBAR PERKERASAN            :       5                   M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           6+600**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5                   M

TYPE PERKERASAN             :       Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 39
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           6+630**

LOKASI :           **STA           6+700**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Beton

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	40

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           6+800**

LOKASI :           **STA           6+900**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	41

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI : STA 6+935

LOKASI : STA 6+985

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	42

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 7+000

LOKASI : STA 7+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	43

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           7+120**

LOKASI :           **STA           7+170**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	44

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           7+200**

LOKASI :           **STA           7+255**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	45

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           7+300**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                    M

TYPE PERKERASAN             :       Beton

LOKASI :           **STA           7+400**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                    M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	46

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           7+500**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                    M

TYPE PERKERASAN             :       Beton

LOKASI :           **STA           7+600**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5                    M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	47

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           7+700**

LOKASI :           **STA           7+800**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	48

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           7+900**

LOKASI :           **STA           8+000**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	49

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           8+100**

KONDISI PERKERASAN           :    **Baik**

LEBAR PERKERASAN            :    **6            M**

TYPE PERKERASAN             :    **Beton**

LOKASI :           **STA           8+150**


KONDISI PERKERASAN           :    **Sedang**

LEBAR PERKERASAN            :    **6            M**

TYPE PERKERASAN             :    **Aspal**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	50

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           8+180**

KONDISI PERKERASAN           :    **Baik**

LEBAR PERKERASAN            :    **6            M**

TYPE PERKERASAN             :    **Beton**

LOKASI :           **STA           8+200**

KONDISI PERKERASAN           :    **Baik**

LEBAR PERKERASAN            :    **6            M**

TYPE PERKERASAN             :    **Beton**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	51

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Gripit - Kalibening**





LOKASI : STA 8+300

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton



LOKASI : STA 8+400

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	52

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 8+500

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton




LOKASI : STA 8+600

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	53

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening





LOKASI : **STA 8+700**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Beton

LOKASI : **STA 8+800**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	54

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI : **STA 8+810**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 8+820**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	55

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI : **STA 8+825**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Beton

LOKASI : **STA 8+900**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	56

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : **STA 9+000**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Beton

LOKASI : **STA 9+080**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 6 M

TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	57

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton


LOKASI : STA 9+150

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 58
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+170

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton


LOKASI : STA 9+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 59
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+300

LOKASI : STA 9+400

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 60
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+500

LOKASI : STA 9+575

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 61
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+600

LOKASI : STA 9+630

KONDISI PERKERASAN : Rusak Ringan  
 LEBAR PERKERASAN : 4 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	62

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+700

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 5 M  
 TYPE PERKERASAN : Beton



LOKASI : STA 9+720

KONDISI PERKERASAN : Rusak Ringan  
 LEBAR PERKERASAN : 5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	63

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 9+800

KONDISI PERKERASAN : Baik



LOKASI : STA 9+900

KONDISI PERKERASAN : Baik



TYPE PERKERASAN : Aspal

TYPE PERKERASAN : Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 66
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 10+400

LOKASI : STA 10+500

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 67
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI : STA 10+600

LOKASI : STA 10+700

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 68
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           10+800**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

LOKASI :           **STA           10+900**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 69
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           11+000**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

LOKASI :           **STA           11+100**


KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M


TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 70
--------------------	----------------------------------	------------------------	----------------------------------	---------------

<b>FOTO SURVEY KONDISI JALAN TAHUN 2025</b>				
<b>RUAS JALAN : Gripit - Kalibening</b>				



08/10/25 14:07:19  
7°15'35"S 109°39'49"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 11+200  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 14:09:19  
7°15'32"S 109°39'50"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 11+300  
#Survei Jalan #DPUPR Kab Banjarnegara


LOKASI :	<b>STA</b>	<b>11+200</b>					
KONDISI PERKERASAN	:	Baik		KONDISI PERKERASAN	:	Baik	
LEBAR PERKERASAN	:	5	M	LEBAR PERKERASAN	:	5	M
TYPE PERKERASAN	:	Aspal		TYPE PERKERASAN	:	Aspal	

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 71
--------------------	----------------------------------	------------------------	----------------------------------	---------------

<b>FOTO SURVEY KONDISI JALAN TAHUN 2025</b>				
<b>RUAS JALAN : Gripit - Kalibening</b>				



08/10/25 14:11:56  
7°15'29"S 109°39'51"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 11+400  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 14:15:26  
7°15'26"S 109°39'52"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 11+500  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :	<b>STA</b>	<b>11+400</b>					
KONDISI PERKERASAN	:	Baik		KONDISI PERKERASAN	:	Baik	
LEBAR PERKERASAN	:	5	M	LEBAR PERKERASAN	:	5	M
TYPE PERKERASAN	:	Aspal		TYPE PERKERASAN	:	Aspal	

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
----------	-----------	------------------------	----------------	---------





FOTO SURVEY KONDISI JALAN TAHUN 2025				
RUAS JALAN : Gripit - Kalibening				
 <p>08/10/25 14:17:02 7°15'22"S 109°39'53"E Kabupaten Banjarnegara #Ruas III. 1 Gripit - Kalibening #STA 11+600 #Survei Jalan #DPUPR Kab Banjarnegara</p>		 <p>08/10/25 14:18:11 7°15'20"S 109°39'51"E Kabupaten Banjarnegara #Ruas III. 1 Gripit - Kalibening #STA 11+700 #Survei Jalan #DPUPR Kab Banjarnegara</p>		
LOKASI :	<b>STA</b>	<b>11+600</b>	LOKASI :	<b>STA</b> <b>11+700</b>
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	: Baik
LEBAR PERKERASAN	:	5 M	LEBAR PERKERASAN	: 5 M
TYPE PERKERASAN	:	Aspal	TYPE PERKERASAN	: Aspal
NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	73


FOTO SURVEY KONDISI JALAN TAHUN 2025				
RUAS JALAN : Gripit - Kalibening				
 <p>08/10/25 14:20:22 7°15'17"S 109°39'50"E Kabupaten Banjarnegara #Ruas III. 1 Gripit - Kalibening #STA 11+800 #Survei Jalan #DPUPR Kab Banjarnegara</p>		 <p>08/10/25 14:22:08 7°15'14"S 109°39'50"E Kabupaten Banjarnegara #Ruas III. 1 Gripit - Kalibening #STA 11+900 #Survei Jalan #DPUPR Kab Banjarnegara</p>		
LOKASI :	<b>STA</b>	<b>11+800</b>	LOKASI :	<b>STA</b> <b>11+900</b>
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	: Baik
LEBAR PERKERASAN	:	5 M	LEBAR PERKERASAN	: 5 M
TYPE PERKERASAN	:	Aspal	TYPE PERKERASAN	: Aspal
NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	74

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



08/10/25 14:24:53  
7°15'12"S 109°39'51"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 12+000  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 14:27:10  
7°15'9"S 109°39'51"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 12+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           12+000**

LOKASI :           **STA           12+100**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 75
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



08/10/25 14:29:20  
7°15'7"S 109°39'52"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 12+200  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 14:32:15  
7°15'6"S 109°39'52"E  
Kabupaten Banjarnegara  
#Ruas III. 1 Gripit - Kalibening  
#STA 12+225  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           12+200**

LOKASI :           **STA           12+225**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 76
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           12+250**

LOKASI :           **STA           12+300**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	77

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           12+400**

LOKASI :           **STA           12+445**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     5            M  
TYPE PERKERASAN             :     Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	78

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           12+500**

LOKASI :           **STA           12+600**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN               :    5            M  
TYPE PERKERASAN                :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN               :    5            M  
TYPE PERKERASAN                :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	79

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           12+700**

LOKASI :           **STA           12+800**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN               :    5            M  
TYPE PERKERASAN                :    Beton

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN               :    5            M  
TYPE PERKERASAN                :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	80

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           12+900**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           13+000**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	81

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+020**

KONDISI PERKERASAN           :    Rusak Berat

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           13+030**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	82

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+070**

LOKASI :           **STA           13+100**

KONDISI PERKERASAN       :     Rusak Ringan  
LEBAR PERKERASAN         :     5                M  
TYPE PERKERASAN           :     Aspal

KONDISI PERKERASAN       :     Sedang  
LEBAR PERKERASAN         :     5                M  
TYPE PERKERASAN           :     Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 83
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+200**

LOKASI :           **STA           13+250**

KONDISI PERKERASAN       :     Sedang  
LEBAR PERKERASAN         :     5                M  
TYPE PERKERASAN           :     Beton

KONDISI PERKERASAN       :     Rusak Ringan  
LEBAR PERKERASAN         :     5                M  
TYPE PERKERASAN           :     Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 84
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+300**

LOKASI :           **STA           13+400**


KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	85

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+500**

LOKASI :           **STA           13+600**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	86

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+700**

LOKASI :           **STA           13+730**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Sedang  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	87

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+740**

LOKASI :           **STA           13+743**

KONDISI PERKERASAN           :    Sedang  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	88

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+770**

LOKASI :           **STA           13+800**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	89

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           13+900**

LOKASI :           **STA           14+000**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	90

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           14+100**

LOKASI :           **STA           14+140**

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       5                    M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5                    M  
TYPE PERKERASAN             :       Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 91
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           14+200**

LOKASI :           **STA           14+300**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5                    M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5                    M  
TYPE PERKERASAN             :       Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 92
--------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           14+400**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

LOKASI :           **STA           14+500**

KONDISI PERKERASAN           :    Baik


LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	93

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           14+580**

KONDISI PERKERASAN           :    Rusak Berat

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           14+600**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	94

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           14+650**

LOKASI :           **STA           14+700**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 95
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           14+800**

LOKASI :           **STA           14+900**


KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 96
--------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





08/10/25 15:53:44  
7°14'24"S 109°38'54"E  
#Ruas III. 1 Gripit - Kalibening  
#STA 15+000  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 15:55:11  
7°14'21"S 109°38'53"E  
#Ruas III. 1 Gripit - Kalibening  
#STA 15+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 15+000

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 15+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	97

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



08/10/25 15:56:51  
7°14'20"S 109°38'50"E  
#Ruas III. 1 Gripit - Kalibening  
#STA 15+200  
#Survei Jalan #DPUPR Kab Banjarnegara



08/10/25 16:00:06  
7°14'17"S 109°38'49"E  
#Ruas III. 1 Gripit - Kalibening  
#STA 15+300  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 15+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 15+300

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	98

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           15+400**

LOKASI :           **STA           15+500**


KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	99

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           15+600**

LOKASI :           **STA           15+620**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       5            M  
TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	100

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           15+700**

LOKASI :           **STA           15+800**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 101
--------------------	----------------------------------	------------------------	----------------------------------	----------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           15+870**

LOKASI :           **STA           15+900**

KONDISI PERKERASAN           :    Rusak Berat  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Rusak Berat  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 1	NAMA RUAS Gripit - Kalibening	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 102
--------------------	----------------------------------	------------------------	----------------------------------	----------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           16+000**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Beton

LOKASI :           **STA           16+100**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	103

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           16+200**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Beton

LOKASI :           **STA           16+300**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       5            M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	104

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           16+310**

LOKASI :           **STA           16+400**

KONDISI PERKERASAN :       Rusak Ringan

KONDISI PERKERASAN :       Sedang

LEBAR PERKERASAN :       5               M

LEBAR PERKERASAN :       5               M

TYPE PERKERASAN :       Aspal

TYPE PERKERASAN :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	105

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           16+500**

LOKASI :           **STA           16+600**

KONDISI PERKERASAN :       Sedang

KONDISI PERKERASAN :       Sedang

LEBAR PERKERASAN :       5               M

LEBAR PERKERASAN :       5               M

TYPE PERKERASAN :       Aspal

TYPE PERKERASAN :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	106

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           16+700**

LOKASI :           **STA           16+800**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Sedang  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	107

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           16+900**

LOKASI :           **STA           17+000**

KONDISI PERKERASAN           :    Rusak Ringan  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	108

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           17+100**

LOKASI :           **STA           17+200**


KONDISI PERKERASAN           :       Rusak Ringan  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	109

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**



LOKASI :           **STA           17+300**

LOKASI :           **STA           17+400**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	110

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Gripit - Kalibening**





LOKASI :           **STA           17+500**

LOKASI :           **STA           17+600**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5                    M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       5                    M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	111

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           17+700**

LOKASI :           **STA           17+800**

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       5                    M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       5                    M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	112

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening





LOKASI :           **STA           17+900**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal



LOKASI :           **STA           18+000**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	113

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gripit - Kalibening



LOKASI :           **STA           18+100**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal



LOKASI :           **STA           18+110**

KONDISI PERKERASAN           :    Sedang

LEBAR PERKERASAN            :    5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 1	Gripit - Kalibening		MELDA & DAHLAN	114