

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+020**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 1
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 2
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **0+300**

LOKASI : **STA** **0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 3
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **0+500**

LOKASI : **STA** **0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 4
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3,5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3,5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 6
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 7
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **1+300**

LOKASI : **STA** **1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 8
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA** **1+500**

LOKASI : **STA** **1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 9
--------------------	------------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 1+700**

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 10
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 1+900**

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 11
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 12
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 13
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 2+500**

LOKASI : **STA 2+600**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 2+700**

LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



27 Okt 2025 10:07:45
7°13'39"S 109°46'49"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 2+900
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 10:08:50
7°13'42"S 109°46'49"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+000
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **2+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **3+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 16
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



27 Okt 2025 10:36:27
7°13'45"S 109°46'48"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+100
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 10:37:40
7°13'49"S 109°46'48"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+200
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **3+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **3+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 17
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



27 Okt 2025 10:38:33
7°13'51"S 109°46'47"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+300
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 10:39:38
7°13'54"S 109°46'44"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+400
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+300**

LOKASI : **STA 3+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal


NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 18
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



27 Okt 2025 10:40:37
7°13'54"S 109°46'42"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+500
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 10:41:41
7°13'56"S 109°46'41"E
Kabupaten Banjarnegara
#Ruas V. 15 Grogol - Biting
#STA 3+600
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+500**

LOKASI : **STA 3+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 19
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 3+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Macadam

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 22
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+300**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 23
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+420**

LOKASI : **STA 4+430**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 24
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+500**

LOKASI : **STA 4+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 25
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+700**

LOKASI : **STA 4+800**


KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Kerikil

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 26
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 4+900**

LOKASI : **STA 5+000**


KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 27
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 5+100**

LOKASI : **STA 5+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	28

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 5+300**

LOKASI : **STA 5+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Macadam


KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Macadam

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	29

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 5+500**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Macadam

LOKASI : **STA 5+600**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 30
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 5+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+800**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 31
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 5+900**

LOKASI : **STA 6+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 32
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 6+040**

LOKASI : **STA 6+050**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 33
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 6+100**

LOKASI : **STA 6+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 34
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 6+300**

LOKASI : **STA 6+400**


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 35
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 6+500**

LOKASI : **STA 6+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	36

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 6+700**

LOKASI : **STA 6+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 15	Grogol - Biting		FIRDAUS & DAMAS	37

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 6+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 7+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 38
---------------------------	-------------------------------------	------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 7+020**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 7+100**


KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 39
---------------------------	-------------------------------------	------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 7+200**

LOKASI : **STA 7+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 40
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 7+400**

LOKASI : **STA 7+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 41
--------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 7+600**

LOKASI : **STA 7+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 42
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 7+800**

LOKASI : **STA 7+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 15	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 43
---------------------------	-------------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 8+000**

LOKASI : **STA 8+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 44
---------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting



LOKASI : **STA 8+200**

LOKASI : **STA 8+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal


KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Grogol - Biting	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 45
---------------------	------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Grogol - Biting





LOKASI : **STA 8+320**

LOKASI : **STA**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Grogol - Biting		FIRDAUS & DAMAS	46