

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 3 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 17	Grogol - Tlagabang		FIRDAUS & DAMAS	1

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 3 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 3 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 17	Grogol - Tlagabang		FIRDAUS & DAMAS	2

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA           0+400**

LOKASI :           **STA           0+500**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       3            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       3            M  
TYPE PERKERASAN             :       Aspal

STA 0+700

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 17	Grogol - Tlagabang		FIRDAUS & DAMAS	3

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA           0+600**

LOKASI :           **STA           0+700**

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       3            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       3            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 17	Grogol - Tlagabang		FIRDAUS & DAMAS	4

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI :           **STA           0+800**

KONDISI PERKERASAN           :    Sedang  
 LEBAR PERKERASAN            :    3            M  
 TYPE PERKERASAN             :    Aspal

LOKASI :           **STA           0+900**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    3            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 17	Grogol - Tlagabang		FIRDAUS & DAMAS	5

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA**           **1+000**

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    3            M  
TYPE PERKERASAN             :    Aspal



LOKASI :           **STA**           **1+100**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    3            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 6
-------------------	---------------------------------	------------------------	-----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA**           **1+200**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    3            M  
TYPE PERKERASAN             :    Aspal

LOKASI :           **STA**           **1+300**

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    3            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 7
-------------------	---------------------------------	------------------------	-----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



27 Okt 2025 09:07:28  
7°11'54"S 109°47'56"E  
Kabupaten Banjarnegara  
#Ruas V. 17 Grogol - Tlagabang  
#STA 1+400  
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 09:08:33  
7°11'53"S 109°47'60"E  
Kabupaten Banjarnegara  
#Ruas V. 17 Grogol - Tlagabang  
#STA 1+500  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA**           **1+400**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     3            M  
TYPE PERKERASAN             :     Aspal

LOKASI :           **STA**           **1+500**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     3            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 8
-------------------	---------------------------------	------------------------	-----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



27 Okt 2025 09:09:33  
7°11'52"S 109°48'3"E  
Kabupaten Banjarnegara  
#Ruas V. 17 Grogol - Tlagabang  
#STA 1+600  
#Survei Jalan #DPUPR Kab Banjarnegara



27 Okt 2025 09:10:29  
7°11'52"S 109°48'6"E  
Kabupaten Banjarnegara  
#Ruas V. 17 Grogol - Tlagabang  
#STA 1+700  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA**           **1+600**

KONDISI PERKERASAN           :     Rusak Ringan  
LEBAR PERKERASAN            :     3            M  
TYPE PERKERASAN             :     Aspal

LOKASI :           **STA**           **1+700**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     3            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 9
-------------------	---------------------------------	------------------------	-----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI :           **STA           1+800**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       3,5            M  
TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           1+900**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       3,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 10
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI :           **STA           2+000**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       3,5            M  
TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           2+100**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4             M  
TYPE PERKERASAN             :       Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 11
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI :           **STA           2+200**

LOKASI :           **STA           2+300**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     4            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     4            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 12
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Grogol - Tlagabang**



LOKASI :           **STA           2+400**

LOKASI :           **STA           2+500**

KONDISI PERKERASAN           :     Rusak Berat  
LEBAR PERKERASAN            :     4            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Rusak Berat  
LEBAR PERKERASAN            :     4            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 13
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA**           **2+600**

LOKASI :           **STA**           **2+700**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 14
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA**           **2+800**

LOKASI :           **STA**           **2+900**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 15
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA           3+000**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4            M  
TYPE PERKERASAN             :       Aspal


LOKASI :           **STA           3+030**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 16
-------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Grogol - Tlagabang



LOKASI :           **STA           3+080**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4            M  
TYPE PERKERASAN             :       Aspal

LOKASI :           **STA**

KONDISI PERKERASAN           :         
LEBAR PERKERASAN            :         
TYPE PERKERASAN             :       

NO. RUAS V. 17	NAMA RUAS Grogol - Tlagabang	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 17
-------------------	---------------------------------	------------------------	-----------------------------------	---------------