

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+000**

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+130**

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+300**

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+500**

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 0+900**

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 6
--------------------------	--	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 1+070**

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 7
--------------------------	--	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 1+130**

LOKASI : **STA 1+140**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 1+200**

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 09:35:48
7,271482S 109,839668E
Kabupaten Wonosobo
#Ruas v. 24 Babadan - Semangkung
#STA 1+400
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 09:38:05
7,270593S 109,839645E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 1+500
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+400**

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 09:42:24
7,270295S 109,840673E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 1+600
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 09:43:57
7,269728S 109,840417E
Kabupaten Wonosobo
#Ruas v. 24 Babadan - Semangkung
#STA 1+700
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+600**

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 09:45:12
7,268838S 109,840380E
Kabupaten Wonosobo
#Ruas v. 24 Babadan - Semangkung
#STA 1+800
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 09:46:28
7,267907S 109,840557E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 1+900
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+800**

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 09:47:37
7,267318S 109,840055E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 2+000
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 09:48:42
7,266923S 109,840315E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 2+050
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+000**

LOKASI : **STA 2+050**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 2+100**

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 2+300**

LOKASI : **STA 2+360**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 2+400**

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 2+600**

LOKASI : **STA 2+660**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkok



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+730**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkok		MELDA & DAHLAN	18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkok



LOKASI : **STA 2+750**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Berat


LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkok		MELDA & DAHLAN	19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 2+900**

LOKASI : **STA 2+920**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 20
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 3+000**

LOKASI : **STA 3+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 21
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 10:09:17
7,262670S 109,843370E
Kabupaten Wonosobo
#Ruas v. 24 Babadan - Semangkung
#STA 3+140
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 10:10:07
7,262685S 109,843397E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 3+143
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+140**

LOKASI : **STA 3+143**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 22
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 10:11:17
7,262832S 109,844012E
Kabupaten Wonosobo
#Ruas v. 24 Babadan - Semangkung
#STA 3+200
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 10:12:27
7,263258S 109,844670E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 3+300
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+200**

LOKASI : **STA 3+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 23
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : STA 3+400

LOKASI : STA 3+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : STA 3+600

LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	25

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 3+800**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 3+900**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	26

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 3+960**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	27

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 4+100**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 28
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 4+300**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 4+400**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 29
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 4+420**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 4+422**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 30
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 4+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 4+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 31
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





22/10/25 10:35:08
7,253328S 109,846448E
#Ruas v. 24 Babadan - Semangkung
#STA 4+700
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 10:36:21
7,252412S 109,846507E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 4+800
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 4+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : STA 4+800

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	32

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 10:37:30
7,251578S 109,846410E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 4+900
#Survei Jalan #DPUPR.Kab Banjarnegara



22/10/25 10:39:05
7,250988S 109,846312E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 4+980
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 4+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : STA 4+980

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	33

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : STA 5+000

LOKASI : STA 5+010

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	34

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : STA 5+050

LOKASI : STA 5+070

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	35

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : STA 5+100

LOKASI : STA 5+170

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 36
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025
 RUAS JALAN : Babadan - Semangkung



LOKASI : STA 5+172

LOKASI : STA 5+200

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 37
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025
 RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 5+250**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+260**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 38
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 5+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 5+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 39
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : STA 5+450

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal



LOKASI : STA 5+500

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 40
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : STA 5+600

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal



LOKASI : STA 5+660

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 41
-------------------	-----------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 5+700**

LOKASI : **STA 5+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	42

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 5+900**

LOKASI : **STA 6+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	43

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : STA 6+100

LOKASI : STA 6+200


KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	44

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : STA 6+300

LOKASI : STA 6+400

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	45

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 6+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 6+560**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DUPUR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	46

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 6+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 6+700**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DUPUR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	47

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





22/10/25 11:54:30
7,238223S 109,848378E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 6+770
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 11:55:27
7,238150S 109,848665E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 6+800
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 6+770**

LOKASI : **STA 6+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	48

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung



22/10/25 11:57:07
7,237245S 109,848515E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 6+900
#Survei Jalan #DPUPR Kab Banjarnegara



22/10/25 11:58:27
7,236412S 109,848715E
Kabupaten Banjarnegara
#Ruas v. 24 Babadan - Semangkung
#STA 7+000
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 6+900**

LOKASI : **STA 7+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 24	Babadan - Semangkung		MELDA & DAHLAN	49

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Babadan - Semangkung





LOKASI : **STA 7+100**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 7+200**


KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 50
--------------------------	--	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025
RUAS JALAN : Babadan - Semangkung



LOKASI : **STA 7+300**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN

LEBAR PERKERASAN

TYPE PERKERASAN

NO. RUAS V. 24	NAMA RUAS Babadan - Semangkung	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 51
--------------------------	--	-------------------------------	---	----------------------