

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+740**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 0+895**

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+000**

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+200**

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+400**

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+600**

LOKASI : **STA 1+700**


KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+780**

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 1+900**

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+100**

LOKASI : **STA 2+105**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+145**

LOKASI : **STA 2+185**

KONDISI PERKERASAN : Rusak Berat
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 2.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+200**

LOKASI : **STA 2+220**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 26	Clapar - Nagasari		MELDA & DAHLAN	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+280**

LOKASI : **STA 2+283**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 16
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+300**

LOKASI : **STA 2+400**


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 17
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+500**

LOKASI : **STA 2+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 18
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+700**

LOKASI : **STA 2+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 19
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 2+900**

LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 20
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+100**

LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 21
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+300**

LOKASI : **STA 3+365**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 22
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+400**

LOKASI : **STA 3+410**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 23
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+500**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 3+600**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 24
-------------------	--------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 3+800**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 2.5 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 25
-------------------	--------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 3+885**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Beton



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Beton

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 26
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Beton



LOKASI : **STA 4+015**

KONDISI PERKERASAN : Rusak Berat (Perbaikan Jembatan)

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Aspal

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 27
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari





03/11/25 11:00:11
7,323150S 109,746240E
Kabupaten Banjarnegara
#Ruas V. 26 Clapar - Nagasari
#STA 4+100
#Survei Jalan #DPUPR Kab Banjarnegara



03/11/25 11:01:54
7,322870S 109,746167E
Kabupaten Banjarnegara
#Ruas V. 26 Clapar - Nagasari
#STA 4+140
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+100**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Beton

LOKASI : **STA 4+140**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Beton

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 28
-------------------	--------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



03/11/25 11:04:05
7,322297S 109,746075E
Kabupaten Banjarnegara
#Ruas V. 26 Clapar - Nagasari
#STA 4+200
#Survei Jalan #DPUPR Kab Banjarnegara



03/11/25 11:05:38
7,321473S 109,746147E
Kabupaten Banjarnegara
#Ruas V. 26 Clapar - Nagasari
#STA 4+300
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Beton

LOKASI : **STA 4+300**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Beton

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 29
-------------------	--------------------------------	------------------------	----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari





LOKASI : **STA 4+370**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Beton



LOKASI : **STA 4+400**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Beton

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 30
--------------------------	---------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Clapar - Nagasari



LOKASI : **STA 4+440**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Beton



LOKASI : **STA**

KONDISI PERKERASAN
 LEBAR PERKERASAN
 TYPE PERKERASAN

NO. RUAS V. 26	NAMA RUAS Clapar - Nagasari	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 31
--------------------------	---------------------------------------	-------------------------------	---	----------------------